

C.L. "BUTCH" OTTER, Governor RICHARD M. ARMSTRONG – Director DEBBY RANSOM, R.N., R.H.1.T — Chief BUREAU OF FACILITY STANDARDS 3232 Elder Street P.O. Box 83720 Boise, Idaho 83720-0336 PHONE: (208) 334-6626 FAX: (208) 364-1888 E-mail: fsb@idhw.state.id.us

August 10, 2007

Adi Mihalache, Administrator Rampart Home Assisted Living 3824 North Rampart Street Boise, ID 83704

Dear Mr. Mihalache:

On August 8, 2007, a Fire Life Safety Survey was conducted at Rampart Home Assisted Living. The facility was found to be providing a safe environment for its residents.

The enclosed form, stating no core issue deficiencies were cited during the survey, is for your records only and need not be returned.

Should you have any questions about our visit, please contact me at (208) 334-6626.

Sincerely,

MARK GRIMES

Supervisor

Facility Fire Safety & Construction Program

MG/lj

Enclosure

(X3) DATE SURVEY STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA (X2) MULTIPLE CONSTRUCTION COMPLETED AND PLAN OF CORRECTION IDENTIFICATION NUMBER: 01 - ENTIRE BUILDING A. BUILDING B. WING_ 13R867 08/08/2007 NAME OF PROVIDER OR SUPPLIER STREET ADDRESS, CITY, STATE, ZIP CODE 3824 N RAMPART STREET RAMPART HOME ASSISTED LIVING BOISE, ID 83704 SUMMARY STATEMENT OF DEFICIENCIES PROVIDER'S PLAN OF CORRECTION (X4) ID (EACH DEFICIENCY MUST BE PRECEDED BY FULL (EACH CORRECTIVE ACTION SHOULD BE COMPLETE DATE PREFIX **PREFIX** REGULATORY OR LSC IDENTIFYING INFORMATION) CROSS-REFERENCED TO THE APPROPRIATE TAG TAG **DEFICIENCY**) R 000 Initial Comments R 000 The facility was found to be in substantial compliance with the fire and life safety requirements of the Rules for Residential or Assisted Living Facilities in Idaho. No core deficiencies were cited during the standard fire/life safety survey conducted on August 8. 2007. The surveyor conducting the survey was: Eric Mundell REHS Health Facility Surveyor Facility Fire/Life Safety & Construction Program

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE (X6) DATE

STATE FORM

Bureau of Facility Standards